## Elcometer 5300

# Ball Type Drying Time Recorder

# **Operating Instructions**



**C E** The Elcometer 5300 Ball Type Drying Time Recorder has been tested in accordance with EU regulations governing Electromagnetic compliance and it meets the required directives.

elcometer<sup>®</sup> is a registered trademark of Elcometer Instruments Ltd.

All other trademarks acknowledged.

© Copyright Elcometer Instruments Ltd. 2005 - 2007.

All rights reserved. No part of this Document may be reproduced, transmitted, transcribed, stored (in a retrieval system or otherwise) or translated into any language, in any form or by any means (electronic, mechanical, magnetic, optical, manual or otherwise) without the prior written permission of Elcometer Instruments Ltd.

A copy of this Instruction Manual is available for download on our Website via www.elcometer.com/downloads.

### CONTENTS

Section			Page		
<b>1</b> 1.1	About your Drying Time Recorder	•••	<b>2</b> 2		
<b>2</b> 2.1 2.2 2.3	Getting started The parts of the instrument The controls Caution	••• ••• •••	<b>3</b> 3 3 4		
3	Testing a specimen		5		
4	Specimen trace analysis		7		
5	Maintenance		8		
6	Technical specification		8		
7	Accessories		9		
8	Related equipment		9		

Thank you for purchasing this Elcometer 5300 Ball Type Drying Time Recorder. Welcome to Elcometer.

Elcometer are world leaders in the design, manufacture and supply of inspection equipment for coatings and concrete. Our products cover all aspects of coating inspection, from development through application to post application inspection.

Your Elcometer 5300 Ball Type Drying Time Recorder, is a world beating product. With the purchase of this product you now have access to the worldwide service and support network of Elcometer. For more information visit our website at www.elcometer.com

### **1 ABOUT YOUR DRYING TIME RECORDER**

The Elcometer 5300 Ball Type Drying Time Recorder is used to determine the drying time of paint and other coatings such as glue, cosmetic products, varnish, inks, biologic material and adhesives.

A layer of the coating is applied to a glass surface and a stainless steel ball is dragged across the glass as the coating dries. At the end of the test the Drying Time Recorder stops automatically and the imprint of the ball on the coating surface is examined to determine the point at which the coating dries.

The Elcometer 5300 Ball Type Drying Time Recorder has ten separate lanes which allow ten different coating formulations to be tested simultaneously.

The load on each ball is 11 g, however this can be increased to 21 g using the supplied weights.

#### 1.1 What the box contains

- Elcometer 5300 Ball Type Drying Time Recorder
- 12 glass strips
- 10 x 10 g weights
- Operating instructions

Your Elcometer 5300 Ball Type Drying Time Recorder is packed in a cardboard and foam package. Please ensure that this packaging is disposed of in an environmentally sensitive manner. Consult your local Environmental Authority for further guidance.

To maximise the benefits of your new Elcometer 5300 Ball Type Drying Time Recorder please take some time to read these Operating Instructions. Do not hesitate to contact Elcometer or your Elcometer supplier if you have any questions.

### **2 GETTING STARTED**

This section of the instructions is intended for first-time users of the Elcometer 5300 Ball Type Drying Time Recorder. It contains information on the parts and controls of the instrument and advice on safe use of the equipment. When you have finished reading this section you will be ready to start using your Elcometer 5300 Ball Type Drying Time Recorder.



#### 2.1 The parts of the instrument

#### Figure 1. Parts of the Elcometer 5300 Ball Type Drying Time Recorder

#### 2.2 The controls

The controls of the instrument are very simple.

#### 2.2.1 Power on/off

To switch the instrument on or off, press the power on/off switch at the rear of the instrument.

#### 2.2.2 Carriage start/stop

To start the carriage, press the carriage start/stop button. The carriage will stop automatically when it reaches the end of the test.

#### 2.2.3 Carriage speed

Your instrument has six carriage speeds which are selected by rotating the carriage speed selector on the left side of the machine.

Carriage speed selector position	Carriage speed (cm per hour)
1	1.2
2	3
3	6
4	12
5	30
6	60

#### 2.2.4 Moving the carriage

To move the carriage to the start position (or any other position), disconnect the carriage from the drive mechanism by rotating the drive coupling knob clockwise. When the carriage is uncoupled, the carriage can be pushed by hand to any position. Rotate the drive coupling knob anticlockwise to reconnect the carriage to the drive mechanism.

#### 2.3 Caution

The Elcometer 5300 Ball Type Drying Time Recorder has been manufactured with your safety in mind. However, improper use can result in damage to the machine.

Please observe the precautions discussed in these operating instructions.



To reduce the risk of electric shock, do not open the housing of the Drying Time Recorder. There are no user-serviceable parts inside.

To reduce the risk of fire or electric shock, do not expose the Drying Time Recorder to rain or excess moisture.

The mains plug on your Drying Time Recorder may be fitted with a fuse. When replacing this fuse, ensure a fuse of the correct rating is used.

### **3 TESTING A SPECIMEN**

- 1. Connect the Drying Time Recorder to the mains supply.
- 2. Switch on the instrument.
- 3. Adjust the height of each ball so that it is perpendicular to the glass specimen and then tighten the thumb screw. In this position the tool provides a load of 11 g  $\pm$  1.5 g. Do the same for all 10 balls.
- Apply the coating to the glass plates using an Elcometer 3505 Cube Film Applicator<sup>a</sup> (Figure 2).



#### Figure 2. Applying the coating using an Elcometer 3505

- 5. Place the glass plates on the instrument.
- 6. Rotate the drive coupling knob clockwise and push the carriage to the 0 (start) position. Rotate the drive coupling knob anti-clockwise to connect the carriage to the drive mechanism.

a. To order an Elcometer 3505 Cube Film Applicator, see "Accessories" on page 9.

7. Rotate all the balls down onto the specimens (Figure 3).



#### Figure 3. Rotate the balls down onto the specimens

- 8. If necessary, add the 10 g weights to increase the load.
- 9. Set the carriage speed using the carriage speed selector.
- 10.Press the carriage stop/start button.

The carriage will travel along the length of the specimens and will stop automatically at the end of its travel.

- 11. At the end of the test, rotate the balls away from the specimens.
- 12. Using the guidelines given in the test standard<sup>b</sup>, examine the specimens to determine the position on the trace where the coating dried. By moving the carriage to this position, the distance can be read from the graduated scale on the body of the instrument. Divide this distance by the carriage speed to give the drying time.
- 13. When the test is completed, clean the balls and glass plates thoroughly.

b. See "Specimen trace analysis" on page 7 for an example of a typical trace analysis.

#### **4 SPECIMEN TRACE ANALYSIS**

The following example of how to analyse the trace left by the balls on a paint coating is taken from the standard NF T 30-037.



Figure 4. Specimen trace analysis

- 1. Levelling: Because paint flows when it is wet, the trace is covered by paint after the ball has passed, therefore no permanent trace is left in the paint film.
- 2. Basic trace: The paint has started to dry.
- 3. **Setting:** The paint film is ruptured by the ball. At this stage dust will not adhere to the paint film.
- 4. **Surface dry:** A skin has formed over the paint. At this stage the paint does not adhere to the ball.
- 5. Dry: The paint is no longer marked by the ball.

#### **5 MAINTENANCE**

The Elcometer 5300 Ball Type Drying Time Recorder is designed to give many years reliable service under normal operating and storage conditions.

Every six months, or sooner when used intensively, lubricate the carriage drive mechanism inside the instrument using SKF ball bearing grease.

The Elcometer 5300 Ball Type Drying Time Recorder does not contain any internal user-serviceable components. In the unlikely event of a fault, the Elcometer 5300 Ball Type Drying Time Recorder should be returned to your local Elcometer supplier or directly to Elcometer.

Details of Elcometer offices around the world are given on the outside cover of these Operating Instructions. Alternatively visit the Elcometer website, www.elcometer.com

#### **6 TECHNICAL SPECIFICATION**

Carriage speed:	1.2 cm (0.5") to 60 cm (24") per hour	
Operating voltage:	UK, 240 V AC 50 Hz EUR, 220 V AC 50 Hz US, 110 V AC 60 Hz	
Power consumption:	100 W	
Fuse rating - plug (if fitted):	4 A	
Fuse rating - machine:	50mA (2 off)	
Dimensions:	860 mm x 420 mm x 170 mm (34" x 16.5" x 6.7")	
Weight:	18 kg (40 lb)	

### 7 ACCESSORIES

The Elcometer 5300 Ball Type Drying Time Recorder is complete with all the items required to get started.

The following accessories are available from your local supplier or direct from Elcometer:

Description	Part Number
Glass strips, set of 10	KT005300P001)
Ball tool, set of 5	KT005300P002
10 g weights, set of 5	KT005300P003
Elcometer 3505 Cube Applicator, 1 reservoir Elcometer 3505 Cube Applicator, 1 reservoir	K0003505M001 (metric) K0US3505M001 (imperial)

### 8 RELATED EQUIPMENT

In addition to the Elcometer 5300 Ball Type Drying Time Recorder, Elcometer produces a wide range of other equipment for determining the physical characteristics of surface coatings.

Users of the Elcometer 5300 Ball Type Drying Time Recorder may also benefit from the following Elcometer products:

- Elcometer Spiral Bar Coaters
- Elcometer Motorised Film Applicators
- Elcometer Leneta Test Charts
- Elcometer Wet Film Gauges
- Elcometer Washability, Brushability and Abrasion Testers
- Elcometer Hardness Testers
- Elcometer Elasticity and Impact Testers

For further information contact Elcometer, your local supplier or visit www.elcometer.com