## elcometer 114 Dewpoint Calculator



This provides accurate values of Relative Humidity (RH) and Dewpoint from the wet and dry bulb temperatures of a Whirling or Sling Hygrometer - such as the Elcometer 116 range.

The range of the Elcometer 114 is -10°C to 50°C and it has an accuracy of ±1% of standard tables.

The calculator includes a <sup>o</sup>C to <sup>o</sup>F converter.

## **Part Number**

ModelDescriptionElcometer 114Elcometer 114 Dewpoint Calculator

Part Number G114----2