

Can be used in accordance with:

FMTS 141A Method 4494



Made of stainless steel, the straight scraper has 10 adjacent notches of increasing clearance. The Elcometer 4270 Sag Tester is used to establish the coatings resistance to sag due to gravity.

After the product has been spread, the contrast chart is immediately placed in vertical position, with the thinnest film at the top. The thickness at which the strips join indicates the tendency to sag.

Part Numbers

Model	Description	Range	Part Number
		μm	
Elcometer 4270/1	4270 Sag Tester	75-300	K0004270M001
Elcometer 4270/2	4270 Sag Tester	25-150	K0004270M002
Elcometer 4270/3	4270 Sag Tester	350-1500	K0004270M203
Elcometer 4270/4	4270 Sag Tester	100-600	K0004270M204
Accessories	Test Charts	See test charts for our complete range	